



ASSOCIATION CONNECTING
ELECTRONICS INDUSTRIES®

IPC-HDBK-830

Guidelines for Design, Selection and Application of Conformal Coatings

Developed by the Conformal Coating Handbook Task Group (5-33c) of
the Cleaning and Coating Committee (5-30) of IPC

Users of this standard are encouraged to participate in the
development of future revisions.

Contact:

IPC
2215 Sanders Road
Northbrook, Illinois
60062-6135
Tel 847 509.9700
Fax 847 509.9798

Table of Contents

1	SCOPE	1	5.2.1	Plating Surfaces	10
1.1	Introduction	1	5.2.2	Alternate Surface Finishes	10
1.2	Purpose	1	5.2.3	Spacing	10
1.3	Scope	1	5.2.4	Solder Mask	10
1.4	Terms and Definitions	1	5.3	Component	10
2	QUALIFICATION AND SPECIFICATION REFERENCES OF CONFORMAL COATINGS	3	5.3.1	Component Material Type	10
2.1	ASTM International Standards	3	5.3.2	Through-Hole Components	11
2.2	Federal Aviation Regulations (FAR)	4	5.3.3	Leaded SMT Components	11
2.3	IPC Standards	4	5.3.4	Leadless SMT Components	11
2.4	Joint Industry Standard	4	5.4	Electrical	12
2.5	Military Standards	4	5.4.1	High Voltage (HV)/High Current (HC)	12
2.6	Underwriters Laboratories	5	5.4.2	RF and Microwave	12
2.7	International Standards	5	5.4.3	High Speed Digital	13
2.7.1	British Standards (DSTAN, UK Defence Standardization)	5	5.4.4	Controlled Impedance	13
2.7.2	IEC Standards	5	5.4.5	EMI/ESD	13
2.8	Original Equipment Manufacturing (OEM) Specification	5	5.5	Coating Coverage	14
3	ENVIRONMENTAL, HEALTH AND SAFETY CONSIDERATIONS	5	5.6	Masking	14
3.1	Emissions	5	5.7	Drawings & Design Guidelines	14
3.2	Disposal of Hazardous Waste	5	5.8	Reworkability/Repairability	14
3.3	Governmental Regulations	5	6	RAW MATERIALS CHARACTERISTICS	15
4	TYPES OF CONFORMAL COATINGS	5	6.1	Viscosity	15
4.1	AR – Acrylic	7	6.1.1	Spindle Measurements	15
4.2	ER – Epoxy	7	6.2	Viscosity vs. Rheology	15
4.3	SR – Silicone	7	6.2.2	Flow Cup Measurements	16
4.4	UR – Polyurethane	7	6.3	Effect of Temperature	16
4.5	XY – Poly-para-xylene (parylene)	8	6.4	Surface Properties	16
4.6	Two-Part Systems (Acrylic/Polyurethane and Other Combinations)	8	7	COMPATIBILITY	16
4.6.1	UV and Solvent Cure	8	7.1	Compatibility with Process Materials	16
4.7	Other Types of Conformal Coatings	8	7.1.1	Solder Masks	16
4.7.1	Fluorocarbon (FC)	8	7.1.2	Flux Residues	17
4.7.2	Perfluoroether	8	7.1.3	Cleaning Media	17
5	DESIGN FOR COATING APPLICATION	9	7.1.4	Plasticizer	17
5.1	Design Philosophy	9	7.1.5	Defoamer	17
5.1.1	Defining Reliability Requirements	9	7.1.6	Mold Release Agent	17
5.1.2	Understanding the Product Life Cycle	9	7.1.7	Marking	17
5.1.3	Defining the Product Environment	9	7.1.8	Temporary Masking	17
5.2	PCBs\Printed Circuit Boards	9	7.2	Inhibition	18
			7.2.1	Types of Inhibition	18
			7.2.2	Location of Inhibition	18
			7.2.3	Causes of Inhibition	18
			7.2.4	Compatibility Check List	19
			7.3	Adhesion	19

7.3.1	Components	19	8.9.6	Catalytic Cure	33
7.3.2	Surface Finishes	19	8.10	Cure Process Considerations	33
7.3.3	Cleanliness	20	8.10.1	Cure By-Products	34
7.4	Interlayer Adhesion	20	8.10.2	Exotherm	34
7.5	Methods of Assessing Compatibility	20	8.10.3	Shrinkage	34
8	PROCESSING	21	8.10.4	Premature Surface Cure/Solvent Entrapment ..	34
8.1	Cleanliness	21	8.10.5	Exceeding Cure Recommendations	34
8.1.1	Cleaning	21	8.10.6	Layering	34
8.1.2	Cleanliness Assessment Techniques	21	8.11	Application Process Monitoring	34
8.1.3	Processing Environment	22	8.12	Inspection Guidelines	35
8.2	Substrate Preparation	22	8.12.1	Magnification	35
8.2.1	Priming	23	8.12.2	UV/Light Source	35
8.2.2	Plasma Treatment	24	8.12.3	Workmanship	35
8.2.3	Mechanical Etching	24	8.13	Environmental, Health and Safety Processing Considerations	35
8.3	Masking	25	8.13.1	Viscosity Adjustment	36
8.3.1	Types of Masks	25	8.13.2	Spraying	36
8.3.2	Manual vs. Automated Masking	25	8.13.3	Dipping and Brushing	36
8.3.3	De-masking	26	8.13.4	Vacuum Deposition	36
8.4	Recommended Coverage	26	8.13.5	Curing	36
8.4.1	Recommended Thickness	26	9	FILM PROPERTIES	36
8.4.2	Uneven Coating Thickness	27	9.1	Appearance/Color	37
8.4.3	Edge and Point Coverage	27	9.2	Dielectric Properties	37
8.4.4	Application Method	27	9.2.1	Dielectric Withstanding Voltage (DWV)	37
8.5	Shadowing/Bridging	27	9.2.2	Insulation Resistance	37
8.5.1	Accessibility Consideration	27	9.2.3	Q-Resonance	37
8.5.2	Curing Consideration	28	9.2.4	Dielectric Constant and Dissipation Factor	37
8.5.3	Shadowing Techniques	28	9.3	Thermal Properties	37
8.5.4	Bridging Techniques	28	9.3.1	Thermal Stability	38
8.6	Viscosity Adjustment	28	9.3.2	Thermal Shock	38
8.6.1	Methods of Viscosity Adjustment	28	9.3.3	Glass Transition Temperature (T_g)	38
8.6.2	Objectives of Viscosity Adjustment	28	9.3.4	Coefficient of Thermal Expansion (CTE)	38
8.7	Application Methods	28	9.3.5	Temperature Gradient	38
8.7.1	Manual Spraying	28	9.4	Flammability	38
8.7.2	Automated Spraying	29	9.5	Flexibility	38
8.7.3	Dipping	30	9.6	Abrasion Resistance	39
8.7.4	Brushing	31	9.7	Coating Creep	39
8.7.5	Selective Coating	31	9.8	Hydrolytic Stability	39
8.7.6	Vacuum Deposition (XY)	32	9.9	Permeability	39
8.8	Multi-Layering	33	9.10	Chemical Compatibility and Chemical Resistance	40
8.9	Cure Mechanisms	33	9.10.1	Fuel Resistance	40
8.9.1	Room Temperature Cure	33	9.10.2	Biological Compatibility	40
8.9.2	Heat Cure	33	9.11	Gas Resistance	40
8.9.3	Heat Accelerable	33	9.12	Corrosion Resistance	40
8.9.4	UV Cure	33	9.13	Fungus Resistance	40
8.9.5	Moisture Cure	33			

9.14 UV Stability 40

9.15 Radiation Resistance 41

9.16 Outgassing 41

10 REWORK AND REPAIR 41

10.1 Removal Methods 41

10.1.1 Chemical 41

10.1.2 Mechanical Abrasion 42

10.1.3 Media Blasting 42

10.1.4 Dry Ice Abrasion 42

10.1.5 Thermal Degradation 42

10.1.6 Laser 42

10.1.7 Plasma 42

10.1.8 Combination Rework Methods 43

10.2 Cleaning After Stripping 43

10.3 Recoating 43

10.4 Environmental, Health and Safety Rework
and Repair Considerations 43

11 END USE ENVIRONMENT 43

11.1 Outdoor Environment 44

11.1.1 Ultraviolet (UV) Radiation 44

11.1.2 Humidity 44

11.1.3 Pollutant Gases 44

11.1.4 Ozone 44

11.1.5 Acid Rain 44

11.1.6 Marine and Coastal Environment 44

11.2 Automotive 45

11.3 Avionics Environment 45

11.3.1 Aircraft on the Ground 45

11.3.2 Equipment Outside The Pressure
Containment Compartment
During Operations 45

11.3.3 Equipment Inside The Pressure
Containment Compartment
During Operations 45

11.4 Space Environment 46

11.5 Medical Environment 46

11.6 Geothermal Environment 46

11.7 Nuclear Biological Chemical Warfare
Environment 46

12 LONG TERM RELIABILITY AND TESTING 46

12.1 Failure Mechanism 46

12.1.1 Wear/Abrasion 46

12.1.2 Loss of Transparency/Discoloration 47

12.1.3 Cracking 47

12.1.4 Loss of Adhesion 47

12.1.5 Bubbles 47

12.1.6 Blistering 47

12.1.7 Mealing 47

12.1.8 Charring 47

12.1.9 Degradation 47

12.1.10 Chemical Attack 47

12.2 Accelerated Testing 48

12.2.1 Test Parameters 48

12.2.2 Examples of Tests 48

13 BIBLIOGRAPHY 48

**APPENDIX A Conformal Coating Comparison
Guide 50**

APPENDIX B Flow Cup Viscosity Measurement 53

APPENDIX C Troubleshooting Guide 54

APPENDIX D Thermal Analysis 58

APPENDIX E Relative Humidity 59

APPENDIX F Time of Wetness 60

APPENDIX G Atmospheric Particulates 61

APPENDIX H Airborne Contaminants 63

APPENDIX I Simulated Acid Rain Test 67

APPENDIX J Coating for Medical Applications 69

**APPENDIX K Example of Stringent Test for Any
Breach in A Conformal Coating 71**

**APPENDIX L Conformal Coating Adhesion Over
Low Residue Fluxes**

**APPENDIX M Low-And No-VOC Conformal
Coatings Over No-Clean Flux
Residues**

INDEX 72

Figures

Figure 4-1 Conformal Coating Family Trees 6

Figure 5-1 Assembly Drawing with Masking
Requirements 15

Figure 8-1 Options of Cleaning Systems According
to Flux Type 22

Figure 8-2 Cure Windows of Primer Cure 23

Figure 8-3 Conditions that Influence the Extent
of Primer Cure 24

Figure 8-4 Influence of Temperature and Humidity 24

Figure 8-5 Masking Tapes 26

Figure 8-6 Masking Boots 26

Figure 8-7 Spray Booth with a Manual Spray Gun 29

Figure 8-8 Nonatomized Curtain Coater 30

Figure 8-9 Swirl Applicator 30

Figure 8-10 Improvements in spray technology now
permit pattern widths as tight as 3.175 mm
[125 mil] for work around sensitive keep-out
areas 30

Figure 8-11 Conveyorized Applicator 31

Figure 8-12 Stand-Alone Batch Applicator 31

Figure 8-13	Automated Applicator	32	Table D-1	Molecular Interpretation	58
Figure 8-14	Dipping Equipment with Smaller PCAs	32	Table D-2	Measurement Methods	58
Figure 8-15	Dipping Equipment with Large PCAs	32	Table E-1	Critical Relative Humidity (CRH) For Several Inorganic Compounds	59
Figure 8-16	Vapor Deposition Polymerization Unit	33	Table F-1	Time of Wetness	60
Figure 8-17	Loss of Conformal Coating Adhesion	35	Table G-1	Deposition Rates for Particles	62
Figure 8-18	Voids in Conformal Coating	36	Table H-1	Ambient Air Pollution Levels	63
Tables					
Table 11-1	Temperature Classifications of Automotive Industry	45	Table H-2	Dry Deposition Measurements	64
Table B-1	Conversion Chart for Flow Cup Viscosity Measurements	53	Table H-3	Highest Levels of Wet Deposition	65
Table C-1	Troubleshooting Guide	54	Table H-4	Concentration of Selected Gaseous Air Constituents in US	65
			Table H-5	Indoor Pollution Levels in the Far East	66
			Table I-1	Acid Rain Formula for Testing Purposes	67

Guidelines for Design, Selection and Application of Conformal Coatings

1 SCOPE

1.1 Introduction Conformal coatings are used in conjunction with printed circuit assemblies (PCAs). The designer and the users of conformal coatings for electronics applications should be aware of the properties of various types of conformal coatings and their interactions with PCAs to protect the PCAs in the end-use environment for the design-life of the PCA (or beyond). This document has been written to assist the designers and users of conformal coatings in understanding the characteristics of various coating types, as well as the factors that can modify those properties when the coatings are applied. Understanding and accounting for these materials can ensure the reliability and function of electronics.

1.2 Purpose The purpose of this handbook is to assist the individuals who either make choices regarding conformal coating or who work in coating operations. This handbook represents the compiled knowledge and experience of the IPC Conformal Coating Handbook Task Group. It is not enough to understand the properties of the various conformal coatings, the user needs to understand what is to be achieved by applying the conformal coating and how to verify that the desired results have been realized.

1.3 Scope Conformal coating, for the purpose of this document, is defined as a thin, transparent, polymeric coating that is applied to the surfaces of PCAs to provide protection from the end-use environment. Typical coating thickness ranges from 12.5 μm [0.49 mil] to 200 μm [7.9 mil].

Processing characteristics and curing mechanisms are dependent on the coating chemistries used. The desired performance characteristics of a conformal coating depend on the application and should be considered when selecting coating materials and coating processes. Users are urged to consult the suppliers for detailed technical data.

This guide enables a user to select a conformal coating based on industry experience and pertinent considerations. It is the responsibility of the user to determine the suitability, via appropriate testing, of the selected coating and application method for a particular end use application.

A conformal coating may have several functions depending on the type of application. The most common are:

- To inhibit current leakage and short circuit due to humidity and contamination from service environment.
- To inhibit corrosion.
- To improve fatigue life of solder joints to leadless packages.

- To inhibit arcing, corona and St. Elmo's Fire.
- To provide mechanical support for small parts that cannot be secured by mechanical means, to prevent damages due to mechanical shock and vibration.

1.4 Terms and Definitions

Acetone – A volatile fragrant flammable liquid ketone $\text{C}_3\text{H}_6\text{O}$ used chiefly as a solvent and in organic synthesis.

Adhesion promotion – The chemical process of preparing a surface to enhance its ability to be bonded to another surface, i.e., a layer of conformal coating.

Adhesion failure – The rupture of an adhesive bond such that the separation appears to be at the adhesive-adherent interface.

Anisotropic – Having properties that vary depending on the direction of measurement.

Anthropogenic – Relating to or resulting from the influence of human beings on nature.

ARUR – Abbreviation standing for acrylic resin and urethane resin combination chemistries.

Bridging – Fillet or meniscus formation of coating around the leads of a component caused by capillary action.

Creep – Strain, deformation, or movement of coatings caused by time and/or temperature.

Cross-linking – The formation of chemical bonds between molecules in a thermosetting resin during a polymerization reaction.

CTE – (Coefficient of Thermal Expansion) Linear dimensional change with respect to an original dimension due to a change in temperature.

Cure – A change in the physical properties of a polymer by a chemical reaction.

Degradation – Decrease in quality or integrity. Loss of desired physical, chemical or electrical properties.

Delamination – A separation between a conformal coating layer and the surface it is adhering to.

De-masking – The process of removing or disengaging a maskant film, tape, boot or plug.

De-wetting – The propensity of the coating material to refuse to wet the surface evenly.

Dielectric constant – The ratio of the capacitance of a configuration of electrodes with a specific material as the dielectric between them to the capacitance of the same